

	Republic of the Philippines	Document No.: BASC-PRO-QSF-02
	<b>BULACAN AGRICULTURAL STATE COLLEGE</b>	Rev. No.: 00
	<b>REQUEST FOR QUOTATION</b>	Effectivity Date: 06/03/2019

Project Reference Number: \_\_\_\_\_

Name of the Project: \_\_\_\_\_

Location of the Project: \_\_\_\_\_

Date: \_\_\_\_\_

Quotation No. \_\_\_\_\_

Company Name: \_\_\_\_\_

Address: \_\_\_\_\_

Please quote your lowest price on the item/s listed below, subject to the General Conditions on the last page, stating the shortest time of delivery and submit your quotation duly signed by your representative not later than \_\_\_\_\_ in the return envelope attached herewith.

\_\_\_\_\_  
MANDY D. BERNARDO  
Procurement Officer

- NOTE:
1. THE APPROVED BUDGET FOR THE CONTRACT IS \_\_\_\_\_.
  2. ALL ENTRIES MUST BE TYPEWRITTEN.
  3. DELIVERY PERIOD WITHIN \_\_\_\_\_ CALENDAR DAYS.
  4. WARRANTY SHALL BE FOR A PERIOD OF three (3) MONTHS FOR NON-EXPENDABLE SUPPLIES ONE (1) YEAR NON-EXPENDABLE SUPPLIES FROM DATE ACCEPTANCE BY THE PROCURING ENTITY.
  5. PRICE VALIDITY SHALL BE FOR A PERIOD OF \_\_\_\_\_ CALENDAR DAYS.
  6. PHILGEPS REGISTRATION CERTIFICATE SHALL BE ATTACHED UPON SUBMISSION OF THE QUOTATION.
  7. BIDDERS SHALL SUBMIT ORIGINAL BROCHURES SHOWING CERTIFICATION OF THE PRODUCT BEING OFFERED.

ITEM No.	Unit	ITEM & DESCRIPTION	QTY	UNIT PRICE	TOTAL
		<b>Repair of New Hostel</b>			
		<b>I. Room 101</b>			
1	set	Replacement of existing hand bidet set	1		
2	set	Replacement of two-piece water closet	1		
3	set	Additional LED Tube light 20watts	1		
4	lot	Replacement of fittings and accessories	1		
5	set	Replacement of floor drain 4"	1		
		<b>II. Room 102</b>			
6	set	Replacement of existing bidet	1		
7	pc	Additional LED Tube light 20watts	1		
8	lot	Replacement of fittings and accessories	1		
9	lot	Repair/replacement of water closet flush tank	1		
10	lot	Repair of water heater	1		
		<b>III. Room 103</b>			
11	set	Replacement of existing bidet	1		
12	lot	Repair/replacement of water closet flush tank	1		
13	lot	Repair of cabinet including paint finish	1		
		<b>IV. Room 104</b>			
14	set	Replacement of existing bidet	1		
15	lot	Repair of lavatory fixtures and fittings (faucet, drain, flexible hose water supply and P-trap)	1		
16	lot	Repair of water closet flush tank	1		
17	lot	Replacement of shower set	1		
		<b>V. Room 201</b>			
18	set	Replacement of existing bidet	1		
19	lot	Repair of water closet flush tank	1		
20	lot	Repair of holes at damaged doors including paint finish	1		
21	sq.m	Repair of damaged ceilings at T&B	1.89		
		<b>VI. Room 202</b>			
		<i>Replacement of all fixtures, fittings and accessories in the T&amp;B:</i>			
22	set	-Water closet	1		
23	set	-Lavatory	1		
24	set	-Shower Set	1		
25	set	-All accessories, fittings and faucets	1		
26	pc	Additional 1-LED Bulb 16watts	1		
27	pc	Additional 1- LED Tube light 20watts	1		
		<b>VII. Room 203</b>			
28	lot	Repair of holes at damaged doors including paint finish	1		
29	lot	Repair of water closet flush tank	1		
		<b>VIII. Room 204</b>			
		<i>Total repair of T&amp;B</i>			
30	set	-Water closet	1		
31	set	-Lavatory	1		
32	set	-Shower Set	1		
33	lot	-All accessories, fittings and faucets	1		
		<b>IX. Room 205</b>			
34	lot	Repair of holes at damaged doors including paint finish	1		
35	set	Repair/replacement of water closet flush tank	1		
36	set	Replacement of existing bidet	1		
37	pc	Additional 1-LED Bulb 16watts	1		
		<b>X. Room 206</b>			
		<i>Total repair of T&amp;B</i>			
38	set	-Water closet	1		
39	set	-Lavatory	1		
40	set	-Shower Set	1		

41	lot	-All accessories, fittings and faucets	1		
42	pc	Additional 1-LED Bulb 16watts	1		
43	pc	Additional 1- LED Tube light 20watts	1		
		<b>XI. Room 207</b>			
44	lot	Repair of holes at damaged doors including paint finish	1		
45	pc	Additional 1-LED Bulb 16watts	1		
		<b>XII. Room 208</b>			
46	lot	Repair/rectification/replacement of damaged pipes causing leakage below room	1		
47	sq.m	Replacement of damaged ceiling including paint finish	3.48		
		Additional 1-LED Bulb 16watts	1		
		<b>XIII. Room 209</b>			
48	lot	Replacement of fittings and accessories	1		
		<b>XIV. Room 210</b>			
49	lot	Replacement of fittings and accessories	1		
		<b>XV. Room 211</b>			
50	lot	Replacement of fittings and accessories	1		
		<b>XVI. Room 212</b>			
51	lot	Replacement of fittings and accessories	1		
		<b>XVII. Others</b>			
52	lot	Repainting and patch up on damaged interior and exterior walls at all rooms	1		
53	sq.m	Repainting of walls at rooms and hallways (topcoat)	924.6		
54	lot	Repair of damaged ceilings at rooms and hallways	1		
55	sq.m	Repainting of ceilings at rooms, lobby and hallways (topcoat only)	784		
56	lot	Repair of damaged tiles	1		
57	sq.m	Repair and repainting of damaged ceiling at Aux Services Office includes repainting	5.76		
		<i>Additional provision of lightings</i>			
58	pcs	LED Bulb 16watts at GF Main entrance	3		
59	pcs	LED Bulb 16watts at GF Hallway	1		
60	pcs	LED Bulb 16watts at GF & 2F Balcony	9		
61	pcs	LED Tube light 20watts at Aux Services Office	3		
62	pcs	LED Bulb 16watts at 2F Lobby	1		
63	lot	Supply and installation of railings at GF entrance	3		
64	pcs	Replacement of room door knobs	16		
65	pcs	Replacement of fire exit door knobs	3		
66	pcs	Replacement of balcony door knobs	6		
67	lot	Repair/additional roof & flashing near Unit212 causing leakage.	1		
68		<b>LABOR</b>			

	Item No.		Item No.
Brand and Model			
Delivery Period:			
Warranty:			
Price Validity:			

After having carefully read and accepted your General Conditions, I/We quote on the item at prices noted above.

Printed Name / Signature
Tel. No. / Cellphone No.
e-mail address
Date